



TEST REPORT

SAMPLE DESCRIPTION : One sample of PVC Tarpaulin 1000 denier
DATE IN : 12 November ,2018 (09:29:00)
DATE OUT : 15 November ,2018

		PART
	TEST	1
Volatile Organic Compounds		NR

P = MEETS BUYER' S REQUIREMENT / F = DOES NOT MEET BUYER' S REQUIREMENT / NR = NO REQUIREMENT / SC=STILL CONTINUES / X=NOT PERFORMED / NA = NOT APPLICABLE / LS = LACK OF SAMPLE / NC = NO COMMENT / I = INCONCLUSIVE / # = SEE RESULT / NF = NEEDS FURTHER TESTING / A = ABSENT / M = MARGINAL ACCEPT / SD = SEE DETAILS ENCLOSED / FS: FURTHER STEPS

This report (including any enclosures and attachments) are prepared for the exclusive use of the Customer(s) named in the report and solely for the purpose for which it is provided and on the basis of instructions and information and/or materials supplied by Intertek's Customer. The test results relate only to the specific items tested and are not intended to be a recommendation for any particular course of action. Customer is responsible for acting as it sees fit on the basis of such results. Unless Intertek provide express prior written consent, no part of this report should be reproduced, distributed or communicated to any third party. Intertek do not accept any liability if this report is used for an alternative purpose from which it is intended, nor do Intertek owe any duty of care to any third party in respect of this report. Except where explicitly agreed in writing, all work and services performed is governed by Intertek Standard Terms and Conditions of Service which is available on request or can be obtained at <http://www.intertek.com/terms>. The reported uncertainty is based on a standard uncertainty multiplied by a coverage factor k=2, providing a level of confidence of approximately 95%. The uncertainty evaluation has been carried out in accordance with ISO/IEC 17025 and TÜRKAK accreditation requirements. Unless otherwise is specified, all Pass or Fail results are given without uncertainty considered. When uncertainty is taken into account, the result may be borderline. Borderline results need to be re-tested to determine their disposition up to customer's decision. Opinions and interpretations expressed herein are outside the scope of TÜRKAK accreditation. Tests marked (*) in this test report are not included in the TÜRKAK accreditation schedule for this laboratory.

PP

Doğan Güneş KILIÇ

Aşkın GÜNERİ

Customer Care Executive

Zeynep AKIN

Chemical Laboratory Manager

Intertek Test Hizmetleri A.Ş.

Merkeç Mahallesi Saman Cad. No:23 Akınlar Plaza Yambasna-34199 İSTANBUL

Phone: +90 212 406 46 46 Fax: +90 212 452 40 65

e-mail : intertekcg.turkiye@intertek.com

<http://www.intertek-turkey.com>



180205684

Test Method	Results	Requirements
-------------	---------	--------------

Volatile Organic Compounds

IHTM AL.2.409 refer to HS-Screening GC/MS

CAS No	Result
--------	--------

Compounds	CAS No	Result	Requirement
Toluene	108-88-3	Not Detected	No Requirement
Dichloromethane	75-09-2	Not Detected	
1,2-Dichloroethane	107-06-2	Not Detected	
Benzene	71-43-2	Not Detected	
Trichloroethylene	79-01-6	Not Detected	
Tetrachloroethylene	127-18-4	Not Detected	
N,N-Dimethylformamide (DMFa)	68-12-2	Not Detected	
Xylene (izomer mix)	1330-20-7	Not Detected	
N,N-Dimethylacetamide (DMAC)	127-19-5	Not Detected	
o-Cresol	95-48-7	Not Detected	
m-Cresol	108-39-4	Not Detected	
p-Cresol	106-44-5	Not Detected	
Naphthalene	91-20-3	Not Detected	
2-Methoxyaniline/ o-Anisidine	90-04-0	Not Detected	
Chloroform	67-66-3	Not Detected	
Carbon Tetrachloride	56-23-5	Not Detected	
1,1-dichloroethene	75-35-4	Not Detected	
1,1,1-trichloroethane	71-55-6	Not Detected	
1,1,2-trichloroethane	79-00-5	Not Detected	
1,1,1,2-tetrachloroethane	630-20-6	Not Detected	
1,1,2,2-tetrachloroethane	79-34-5	Not Detected	
Pentachloroethane	76-01-7	Not Detected	
1,2-Dichlorobenzene	95-50-1	Not Detected	
1,3-Dichlorobenzene	541-73-1	Not Detected	
1,4-Dichlorobenzene	106-46-7	Not Detected	
Phenol	108-95-2	Not Detected	
1,4-Dioxane	123-91-1	Not Detected	
N-Nitrosodimethylamine (NDMA)	62-75-9	Not Detected	
Bis(2-methoxyethyl)ether / Diethylene glycol dimethyl ether / Diglyme	111-96-6	Not Detected	
N-Methylpyrrolidone	872-50-4	Not Detected	
Styrene	100-42-5	Not Detected	
1,2-dichloropropane	78-87-5	Not Detected	
Vinylcyclohexene (4-vinyl-1-cyclohexene)	100-40-3	Not Detected	
Ethylbenzene	100-41-4	Not Detected	
o-Xylene	95-47-6	Not Detected	
m-Xylene	108-38-3	Not Detected	
p-Xylene	106-42-3	Not Detected	

Intertek Test Hizmetleri A.S.

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : intertekg.turkiye@intertek.com

<http://www.intertek-turkey.com>

Test Method	Results	Requirements
-------------	---------	--------------

Volatile Organic Compounds

IHTM AL.2.409 refer to HS-Screening GC/MS

	<u>CAS No</u>	<u>Result</u>	
Cylohexanone	108-94-1	Not Detected	No Requirement
Methyl ethyl ketone (MEK)	78-93-3	Not Detected	
Asetone	67-64-1	Not Detected	

ppm (part per million) =mg / kg
< =Less Than

Detection Limit : 5 ppm

Estimated Total Uncertainty=(Textile,Plastic:±9%; Textile:±8%)



END OF TEST REPORT

Intertek Test Hizmetleri A.S.

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna-34197 /ISTANBUL

Phone : +90 212 496 46 46 Fax: +90 212 452 80 55

e-mail : interteckg.turkiye@intertek.com

<http://www.intertek-turkey.com>